TELETYPE CORPORATION CHICAGO, ILLINOIS, U.S.A.

EE-525 ISSUE 1 JANUARY, 1946

CHANGES AND ADDITIONS TO PARTS BULLETINS

1001	Issue 1	1067 Issue	2	1090	Issue 2
1012	Issue 2	1080 Issue	1	1093	Issue 1
1038	Issue 2	1082 Issue	2	1100	Issue 2
1052	Issue 1	1088 Issue	2	1117	Issue 2
1064	Issue 2	1089 Issue	1		

The punch block assemblies shown in the above bulletins have been redesigned and assigned new assembly numbers. Old style punch block assemblies are no longer furnished. On orders for old style blocks, new style assemblies which are fully interchangeable with the old style will be furnished.

The sketches below illustrate the difference between the old and new style assemblies, and it should be noted that the shedder and wearing strip are replaced by a retractor plate, and the shedder guides are not used. The shedder and wearing strip are no longer being furnished. When it is desired to replace a shedder or wearing strip, a retractor plate should be ordered instead.

The chart below may be used to determine the new style punch block assembly number which replaces an old style, and which retractor plate must be ordered to replace the old style shedder, and/or wearing strip.

