TELETYPE CORPORATION Skokie, Illinois, U.S.A.

SPECIFICATION 50822S Issue 1, January 1976

INSTRUCTIONS FOR INSTALLING THE 402178 MODIFICATION KIT TO INTERFACE A MODEL 40 SET WITH BELL SYSTEM 113A OR 113D DATA SETS

1. GENERAL

1.01 The 402178 modification kit provides the necessary strap and tool to convert a Model 40 Keyboard/Display Set equipped with a 40C204 controller for operation with a 113A or 113D Data Set.

1.02 This modification kit consists of an electrical strap installed within the 341896 EIA cable supplied with the KD Set. A tool is provided to remove the contacts already in the position where the strap contacts are to be installed.

1.03 The 402178 modification kit consists of:



341983 Contact Tool (1)



402185 Electrical Strap (1)

RTTY ELECTRONICS TELETYPE=Sales-Service-Parts PO Box 20101 El Sobrante, Ca. 94820. (510)222-3102 mr_rtty@pacbell.net

© 1975 by Teletype Corporation All rights reserved Printed in U.S.A.

2. INSTALLATION

2.01 The connector of the 341896 EIA cable which mates with the Model 40 Data Set controller connector must be changed as follows:



(5) Install the female pins of the 402185 electrical strap in positions 6, 8, and 20 of the connector.



- (6) Connect the white-red lead previously removed to the remaining male pin of the 402185 electrical strap. Tape connection after inserting.
- (7) Reinstall cable strain relief.
- 3. TESTING

1

- 3.01 Testing consists of making a continuity test on the 341896 EIA cable assembly using the above actual wiring diagram.
- 3.02 For an on-line test, place a call to a Dața Test Center and follow the Data Test Center instructions.

Page 3 3 Pages